

Fig. 1

Stufung	1.75	1.26	1.31	1.38	1.37	1.28	Spreizung	7
i-Gang	5.47	3.13	2.48	1.90	1.37	1.00	0.78	-3.6
SE/Gg	1	2	3	4	5	6	7	-R1
03	X	X	X	X	X			
04	X							X
05		X					X	
14					X	X	X	
15				X		X		X
45			X					

Fig. 2




Fig. 3

Stufung	1.75	1.26	1.31	1.38	1.37	1.28	Spreizung	7
i-Gang	5.47	3.13	2.48	1.90	1.37	1.00	0.78	-3.6
SE/Gg	1	2	3	4	5	6	7	R1
03	X	X	X	X	X			
04	X							X
05		X					X	
14					X	X	X	
15				X		X		X
45			X					

Fig. 4




Fig. 5




Fig. 6